

IGNITION SYSTEM

GENERAL

OUTLINE OF CHANGE

The spark plug of vehicles with 6G75-MPI engine has been changed. The service procedures are the same as vehicles for Taiwan.